

LAB ID # 11216  
LAB ID # 11827

# Benchmark Analytics, Inc. Eastern Division

2566 Pennsylvania Ave.  
Sayre, PA 18840

Work Order: 10052872

Phone: (570) 888-0169  
Fax: (570) 888-0717

SEND DATA TO:

NAME: Dana Harris  
COMPANY: Wellsville Water Treatment Plant  
ADDRESS: 111 W. State Street  
Wellsville, NY 14895

WO#: 10052872

PAGE: 1 of 1

PO#:

PWS ID# 0200327-Allegany Co. DO

PHONE: (585) 593-3333  
FAX: (585) 593-5864

## TEST REPORT

TOC Testing

RECEIVED FOR LAB BY: WCB

DATE: 05/19/2010 17:00

Page 1 of 1

Test	Result	Method	Reg Limit	Analysis Start	Analysis End	Analyst *
SAMPLE: <b>Source</b> Lab ID: 10052872-001A Grab						
SAMPLED BY: DH Sample Time: 05/19/2010 9:00						
Total Organic Carbon	3.0 mg/L	SM5310C		05/24/10 14:00	05/25/10	NFM-SA
SAMPLE: <b>Entry Point</b> Lab ID: 10052872-002A Grab						
SAMPLED BY: DH Sample Time: 05/19/2010 9:00						
Total Organic Carbon	1.4 mg/L	SM5310C	MCL	05/24/10 14:00	05/25/10	NFM-SA

REMARKS:

Where the analytical method has been performed under NELAP certification, the analysis has met all of the requirements of the NELAC standard unless otherwise noted on the Analytical Report.

\* CV = Benchmark Analytics, Inc. Center Valley, PA; SA = Benchmark Analytics, Inc. Sayre, PA

MANAGER

*Carrie M. Davis*

DATE: 5/28/2010